

Belle River Watershed Management Plan

July 2015

www.sccwater.org




TABLE OF CONTENTS

| | |
|---|----|
| Table of Contents..... | i |
| Appendices..... | v |
| List of Figures..... | vi |
| List of Tables | ix |
| Abbreviations..... | xi |
| 1 Chapter 1 - Watershed Description..... | 1 |
| 1.1 Watershed Management Planning | 1 |
| 1.2 Geographical Scope | 1 |
| 1.2.1 River Zones..... | 3 |
| 1.2.2 Subwatersheds..... | 6 |
| 1.2.3 Belle River Intercounty Drain..... | 8 |
| 1.2.4 Topography | 9 |
| 1.2.5 Soils..... | 11 |
| 1.3 Hydrology | 12 |
| 1.3.1 Dams and Barriers..... | 13 |
| 1.3.2 Wetlands | 15 |
| 1.3.3 Baseflows..... | 17 |
| 1.3.4 Flashiness and Flood Flows | 20 |
| 1.3.5 Channelization | 21 |
| 1.4 Significant Natural Features..... | 22 |
| 1.4.1 Existing Parks and Conservation Areas | 22 |
| 1.4.2 Wetlands | 23 |
| 1.4.3 Threatened and Endangered Species..... | 24 |
| 1.4.4 Farmland | 25 |
| 1.5 Land Use, Growth Trends, and Master Plan Analysis | 26 |
| 1.5.1 Land Use Analysis | 26 |
| 1.5.2 Growth Trends | 29 |
| 1.5.3 Master Plan Analysis | 31 |
| 2 Chapter 2 – Water Quality Conditions..... | 38 |
| 2.1 Water Quality..... | 39 |

| | | |
|--------|---|----|
| 2.1.1 | Total Maximum Daily Load (TMDL)..... | 40 |
| 2.1.2 | Biological Oxygen Demand (BOD)..... | 41 |
| 2.1.3 | Turbidity and Suspended Solids | 42 |
| 2.1.4 | Phosphorus..... | 44 |
| 2.1.5 | Nitrogen | 45 |
| 2.1.6 | Chloride..... | 46 |
| 2.1.7 | Surface Water Temperature | 47 |
| 2.1.8 | Pesticides..... | 47 |
| 2.1.9 | Pathogenic Microorganisms..... | 48 |
| 2.1.10 | Dumping and Litter..... | 49 |
| 2.1.11 | Nonpoint Source Pollutants | 50 |
| 2.2 | Biomonitoring | 51 |
| 2.2.1 | Aquatic Habitat | 52 |
| 2.2.2 | Fisheries | 53 |
| 2.2.3 | Macroinvertebrates..... | 57 |
| 2.2.4 | Mussels | 60 |
| 2.3 | Sediment Loading & Channel Stability | 62 |
| 2.3.1 | Stable Reference Reach Areas | 63 |
| 2.3.2 | Bed Erosion..... | 65 |
| 2.3.3 | Streambank Erosion | 66 |
| 2.3.4 | Channel Enlargement..... | 68 |
| 2.3.5 | Hillslope Failures | 68 |
| 2.3.6 | Channel Blockages..... | 70 |
| 2.3.7 | Road Stream Crossings | 71 |
| 3 | Chapter 3 – Prioritized Pollutants, Critical Areas, and Priority Areas..... | 74 |
| 3.1 | Prioritized Pollutants and Watershed Concerns | 74 |
| 3.2 | Priority Areas and Critical Areas | 76 |
| 3.2.1 | Priority Areas | 76 |
| 3.2.2 | Critical Areas | 80 |
| 3.3 | Critical Sources of Prioritized Pollutants throughout the Watershed..... | 83 |
| 3.3.1 | Sediment | 83 |
| 3.3.2 | Bacteria | 86 |
| 3.3.3 | Nutrients..... | 87 |

| | | |
|-------|---|-----|
| 3.3.4 | Total Dissolved Solids | 88 |
| 3.3.5 | Toxic Pollutants | 88 |
| 3.4 | Implementation Strategy | 89 |
| 4 | Chapter 4 - Designated and Desired Uses | 90 |
| 4.1 | Designated Uses of Michigan Waterways | 90 |
| 4.2 | Desired Uses of the Belle River Watershed..... | 92 |
| 4.3 | St. Clair River Remedial Action Plan | 93 |
| 5 | Chapter 5 – Watershed Goals and Objectives..... | 96 |
| 5.1 | Long-Term Goals and Short-Term Objectives | 98 |
| 5.2 | Additional Considerations..... | 111 |
| 6 | Chapter 6 – Best Management Practices..... | 112 |
| 6.1 | Management Alternatives | 112 |
| 6.1.1 | Managerial & Structural Actions: Agricultural Runoff Controls..... | 113 |
| 6.1.2 | Stream and Drain Runoff Controls | 116 |
| 6.1.3 | Structural & Vegetative Actions: Stormwater Runoff Controls | 121 |
| 6.1.4 | Managerial Actions: Illicit Discharge Elimination | 130 |
| 6.1.5 | Managerial Actions: Public Education, Outreach, & Participation | 132 |
| 6.1.6 | Managerial Actions: Ordinances & Policies | 138 |
| 6.1.7 | Managerial Actions: Studies and Plans..... | 144 |
| 6.1.8 | Watershed Plan Implementation | 146 |
| 6.2 | Estimated Costs of Management Alternatives | 147 |
| 7 | Chapter 7 – Watershed Action Plan..... | 166 |
| 7.1 | Best Management Practice Implementation Schedule | 166 |
| 7.2 | Action Plan Matrix..... | 167 |
| 7.3 | Priority Projects | 167 |
| 8 | Chapter 8 – Public Education and Participation | 188 |
| 8.1 | Public Involvement Process | 188 |
| 8.2 | Watershed Advisory Group and Subcommittee Meetings | 189 |
| 8.3 | Public Meetings | 191 |
| 8.4 | Public Opinion Survey Results | 193 |
| 8.4.1 | Value of Water Quality | 193 |
| 8.4.2 | Sources of Water Pollution | 194 |
| 8.4.3 | Practices to Improve Water Quality | 195 |

| | | |
|-------|---|-----|
| 8.4.4 | Willingness to Take Action..... | 196 |
| 8.4.5 | Farm Operations..... | 196 |
| 8.4.6 | Demographics | 197 |
| 8.4.7 | Best Ways to Inform Residents..... | 197 |
| 8.4.8 | Comments | 198 |
| 8.5 | Involvement and Education Implementation Strategy | 198 |
| 8.6 | Priority Education Recommendations | 204 |
| 8.6.1 | Prioritized Water Quality Education Recommendations | 204 |
| 8.7 | Project Partnerships | 205 |
| 9 | Chapter 9 – Evaluation Process | 208 |
| 9.1 | Methods of Evaluation | 208 |
| 9.1.1 | Programmatic Indicators/BMP Results..... | 209 |
| 9.1.2 | Photographic Surveys | 209 |
| 9.1.3 | Stakeholder Surveys/Social Indicators..... | 209 |
| 9.1.4 | Water Quality Indicators | 210 |
| 9.1.5 | Biological Indicators | 211 |
| 9.2 | Monitoring Strategy | 212 |
| 9.3 | Adaptive Management | 212 |
| 9.4 | Summary of Methods for Evaluating Progress and Measurable Goals | 213 |

APPENDICES

| | |
|------------|---|
| Appendix A | References |
| Appendix B | Maps |
| Appendix C | Resource Directory |
| Appendix D | Belle River Watershed Hydrologic Study |
| Appendix E | Landscape Level Wetland Functional Assessment |
| Appendix F | Data Gap Analysis |
| Appendix G | Non-Point Source Pollutant Identification |
| Appendix H | Belle River Watershed Assessment of River Stability and Sediment Supply |
| Appendix I | Belle River Management Plan for Large Woody Material |
| Appendix J | Critical Project Profiles |
| Appendix K | Belle River Watershed Land Prioritization Model |
| Appendix L | Public Participation Survey |

LIST OF FIGURES

- Figure 1.1 Overview of the Belle River Watershed
- Figure 1.2 Belle River system by zones
- Figure 1.3 North Branch of the Belle River in Zone 1, Lions Park in Imlay City
- Figure 1.4 Belle River in Zone 2, Columbus Township Roadside Park
- Figure 1.5 Belle River in Zone 3, Marine City
- Figure 1.6 Belle River subwatersheds
- Figure 1.7 The Belle River Intercounty Drain
- Figure 1.8 Long topographical profile of the Belle River
- Figure 1.9 Soil hydrogroups in the Belle River Watershed
- Figure 1.10 Belle River circa 1900, Marine City (Source: Marine City Historical Society)
- Figure 1.11 Map of existing and historic dams and hydraulic structures
- Figure 1.12 Former Radike Dam looking upstream at Indianhead Trail in 1937
- Figure 1.13 Existing wetland area near the N. Branch Belle River in Imlay City
- Figure 1.14 Pre-settlement vs. 2005 wetland areas providing fish habitat
- Figure 1.15 Butler Drain (Berlin Twp. between Sperry & Berville Rd.) with no flow (Source: SCCDC)
- Figure 1.16 Discharge data for the Belle River at Memphis (USGS, 2013)
- Figure 1.17 Decadal flow duration curves for North Branch Belle River at Imlay City, MI
- Figure 1.18 Decadal flow duration curve analysis for Belle River at Memphis
- Figure 1.19 Hydrologic critical areas (MDEQ, 2012 in Appendix D)
- Figure 1.20 Example of historic dredging practices in St. Clair County
- Figure 1.21 Musiel Park in City of Memphis, St. Clair County
- Figure 1.22 China Township Park public access site, St. Clair County
- Figure 1.23 An eastern sand darter from the Belle River (MDNR, 2009)
- Figure 1.24 Federally endangered and state endangered mussels in the Lower Belle River (MDNR, 2011)
- Figure 1.25 Prime agricultural lands in St. Clair County
- Figure 1.26 Land cover in the Belle River Watershed in 1800
- Figure 1.27 Land cover in the Belle River Watershed in 1978
- Figure 1.28 Land cover in the Belle River Watershed in 2005
- Figure 2.1 Fish consumption advisory sign for the St. Clair River Area of Concern
- Figure 2.2 Dissolved Oxygen TMDL areas in the Belle River Watershed
- Figure 2.3 Estimated monthly biological oxygen demand loads near Marine City (USGS, 2007)
- Figure 2.4 Estimated monthly phosphorus loads near Marine City (USGS, 2007)
- Figure 2.5 Estimated monthly total nitrogen loads near Marine City (USGS, 2007)
- Figure 2.6 Estimated monthly chloride loads near Marine City (USGS, 2007)
- Figure 2.7 Debris in Currier Drain (Berlin Twp., Burt Rd.)
- Figure 2.8 Trash in Hannah Drain (Berlin Twp., Burt Rd.)
- Figure 2.9 2012 Belle River GLEAS habitat scores
- Figure 2.10 MDNR fish shocking in the Belle River, Kronner Road, Columbus Township
- Figure 2.11 2008 Belle River GLEAS fish scores
- Figure 2.12 Belle River Watershed trout streams shown in purple (Appendix D)

Figure 2.13 Steelhead stocking in the Belle River

Figure 2.14 Representative photographs taken in the Belle River Watershed in July/August 2012: Top Left) Belle River at St. Clair Hwy (Station 28), Top Right) Belle River at Kronner Road (Station 29), Bottom Left) N. Br. Belle River at Newark Road d/s of Pinnacle (Vlastic) Foods outfall (Station 32), and Bottom Right) N. Br. Belle River at Newark Road u/s of Pinnacle (Vlastic) Foods outfall (Station 33) (MDEQ, 2013)

Figure 2.15 2012 Belle River GLEAS macroinvertebrate scores

Figure 2.16 Belle Rive report card for the MiCorps volunteer stream monitoring program

Figure 2.17 Volunteers monitoring the Belle River,

Figure 2.18 Volunteers monitoring the Belle River, Memphis

Figure 2.19 Sampling locations on the Belle River from 2011 MDNR studies

Figure 2.20 Belle River mussel surveys, St. Clair Township

Figure 2.21 Reference Reach III on the Belle River upstream of Ashery Creek to Konner Rd.

Figure 2.22 Reference Reach V on an unnamed tributary of the Belle River N. of St. Clair Hwy.

Figure 2.23 Localized regional curve of drainage area vs. bankfull discharge

Figure 2.24 Example of excessive deposition in Currier Drain (Berlin Twp.)

Figure 2.25 Example of channel downcutting in Schneider-China Drain (China Twp.)

Figure 2.26 Hillslope failures on Belle River upstream of the Memphis gauge station

Figure 2.27 Hillslope failure on Belle River downstream of Memphis gauge station

Figure 2.28 Extensive logjam on the Belle River, Columbus Township

Figure 2.29 Jerome Creek at Church Road crossing (facing upstream)

Figure 2.30 Belle River at Palms Road crossing (facing upstream)

Figure 3.1 Belle River Coal-Fired Power Plant in E. China Township (Source: J. Smith, Times Herald)

Figure 3.2 Prioritized parcel for woodland and wetland preservation, Lapeer County (Source: SRLC)

Figure 3.3 Priority parcel for prime agricultural land, Lapeer County

Figure 3.4 Blueways Trail Map of the Belle River Route

Figure 3.5 Kayakers on the Belle River Blueway Trail

Figure 3.6 Priority parcels to improve water quality identified in the SRLC study

Figure 3.7 Typical channelized and modified tributaries in agricultural areas

Figure 3.8 Schematic of channelized and meandering drainage courses

Figure 3.9 Non-point source critical areas in the Belle River Watershed headwaters

Figure 3.10 Farmed, unstable headwater tributary of the Belle River

Figure 3.11 Sedimentation in a tributary to Belle River

Figure 3.12 Evidence of streambank erosion along the Lower Belle River

Figure 3.13 Erosion hazard areas in the Belle River Watershed based on soils

Figure 4.1 The Belle River is a direct tributary to the St. Clair River

Figure 4.2 A recently completed fish and wildlife habitat shoreline restoration project in Cottrellville Township for the St. Clair River Area of Concern

Figure 5.1 Broad-level view of the stream function pyramid

Figure 5.2 Detailed view of the stream functions pyramid

Figure 5.3 A riparian buffer is needed to stabilize this streambank at

Figure 5.4 SCC PARC streambank stabilization demonstration project using large woody material from the Belle River, Columbus County Park

Figure 5.5 SEMCOG has developed the Seven Simple Steps to Clean Water campaign materials

Figure 5.6 Volunteers conduct a stream clean-up, Cottrellville Township

Figure 5.7 An ADA canoe/kayak launch provided by SCC PARC

Figure 5.8 Paddler on the Belle River Blueway Trail (Source: Marine City)

Figure 6.1 Examples of Michigan cover crops, crimson clover and buckwheat (Source: MSU Extension)

Figure 6.2 Livestock exclusion fencing protects riparian vegetation and prevents excessive streambank erosion (Source: Virginia Department of Conservation)

Figure 6.3 Crop residue prevents soil from washing away during precipitation events (Source: US EPA)

Figure 6.4 Drainage management practices allow farmers to drain only as needed (Source: Purdue University)

Figure 6.5 Large woody material removal and bank stabilization in Columbus County Park

Figure 6.6 Example of a vegetative buffer in E. China Township

Figure 6.7 Example of riprap shoreline stabilization practices

Figure 6.8 Typical two-stage drainage ditch design (Source: The Nature Conservancy)

Figure 6.9 Culvert in poor condition on Rayment Drain in Subwatershed 5

Figure 6.10 Example of a wet detention pond to detain stormwater (Source: US EPA)

Figure 6.11 Vegetated green roof at the Ford Motor Company River Rouge Plant

Figure 6.12 An example of a rain garden to increase rainwater infiltration

Figure 6.13 Typical permeable pavement design (Source: Smith, 2009)

Figure 6.14 Example of Michigan native grasses and wildflowers (Source: Native Connections)

Figure 6.15 A riparian buffer lining a farm creek (Source: USDA NRCS)

Figure 6.16 SCCHD sanitarians investigating an illicit discharge

Figure 6.17 A watershed road sign installed on King Road at the Baird Drain bridge crossing, China Township

Figure 6.18 Volunteers collecting macroinvertebrates as part of the Stream Leaders program (Source: Friends of the St. Clair River)

Figure 6.19 An example of a volunteer placing a permanent storm drain marker to increase watershed awareness

Figure 6.20 The SCCHD hosts an annual River Day event in June across St. Clair County's waterways

Figure 6.21 Example of a riparian buffer (Source: USDA NRCS)

Figure 6.22 Example of a standard subdivision parcel arrangement (left) and a cluster subdivision arrangement (right)

Figure 6.23 A silt fence is an example of a Soil Erosion and Sedimentation Control BMP (Source: SCCHD)

Figure 7.1 Priority reduction sites and priority subwatersheds for wetland restoration

Figure 7.2 Priority wetland restoration sites in the DO TMDL area

Figure 8.1 Stream Leader volunteers conducted macroinvertebrate monitoring on the Belle River at the Indian Trail Road Bridge in China Township.

Figure 8.2 Public meeting held on January 28 at Southeast Michigan Conservation Club in East China Township

LIST OF TABLES

| | |
|------------|---|
| Table 1.1 | Belle River subwatersheds |
| Table 1.2 | Explanation of soil hydrogroups |
| Table 1.3 | Existing and historic dams and hydraulic structures in the Belle River Watershed |
| Table 1.4 | Predicted change in functional capacity due to loss of wetlands since pre-settlement |
| Table 1.5 | Critical minimum Belle River dry season flows based on the Tennant Method |
| Table 1.6 | Belle River Watershed land cover comparison |
| Table 1.7 | More specific land uses from 1800 to 2005 |
| Table 1.8 | Acres of land cover |
| Table 1.9 | Population change from 2000 to 2010 |
| Table 1.10 | Watershed growth - 2000 to 2030 forecast |
| Table 2.1 | Belle and North Branch Belle Rivers DO TMDL reaches |
| Table 2.2 | Results of 2013 pollutant source identification surveys |
| Table 2.3 | Summary of E. coli monitoring results from 2008 to 2011 (cfu/mL) |
| Table 2.4 | Upland nonpoint sources area loadings from inadequate riparian buffers |
| Table 2.5 | Upland nonpoint source area loadings from nonpoint agricultural sources |
| Table 2.6 | Mussel species found during MDNR surveys at four sampling locations. State and federal status are indicated with the following abbreviations: E=endangered; T= threatened; SC=species of special concern. |
| Table 2.7 | Actively downcutting water courses in the Belle River Watershed |
| Table 2.8 | In-stream nonpoint source loadings from streambank erosion |
| Table 2.9 | Upland nonpoint sources area loadings from streambank erosion |
| Table 2.10 | Upland nonpoint source area loadings from gully erosion |
| Table 2.11 | In-stream nonpoint source loadings from hillslope failures |
| Table 2.12 | Upland nonpoint source area loadings from stream crossings |
| Table 3.1 | Prioritized pollutants and watershed concerns in the Belle River Watershed |
| Table 3.2 | Summary of 303(d) listed areas in the Belle River Watershed (MDEQ, 2004) |
| Table 3.3 | Ranking of upper 50% of subwatersheds by total phosphorus as calculated by the STEPL model |
| Table 3.4 | DTE Energy 2013 chemical releases from the Belle River plant |
| Table 4.1 | Definitions for the designated uses for water |
| Table 4.2 | Belle River impaired designated uses |
| Table 4.3 | Summary of desired uses for the Belle River Watershed |
| Table 5.1 | Summary of long-term goals |
| Table 5.2 | Long-term goals and measurable objectives for the Belle River Watershed |
| Table 5.3 | St. Clair River Remedial Action Plan (RAP) goals |
| Table 6.1 | BMPs to address pollutants and sources, including estimated costs |
| Table 7.1 | Watershed Action Plan Matrix for the Belle River Watershed |
| Table 7.2 | Priority projects to address the goals of the Belle River Watershed Management Plan |
| Table 7.3 | Priority project sites to reduce sediment and nutrient loading in the TMDL area. Projects are prioritized based on the quantity of sediment load reduction. See project # in Appendix J for more details. |

Table 7.4 Priority projects for critical ecosystem conservation
Table 7.5 Large woody material management sites identified in the 2013 LWM assessment of the Belle River. See project # in Appendix J for more details.
Table 7.6 Priority river restoration projects in or near existing parks on the Belle River. See project # in Appendix J for more details.
Table 8.1 Participants in the Belle River Watershed Advisory Group
Table 8.2 Survey results from question regarding trusted sources for water quality information
Table 8.3 I&E strategy, including delivery mechanism, target audience, and evaluation mechanism
Table 8.4 I&E strategy to address pollutant causes in impaired subwatersheds
Table 8.5 Watershed-wide water quality and natural resource protection organizations
Table 9.1 Water quality standards associated with water quality parameters
Table 9.2 Targets for assessment of fish and macroinvertebrate assemblages
Table 9.3 Methods of evaluation and evaluation schedule for each method
Table 9.4 Evaluation methods to address goals and priority projects
Table 9.5 Monitoring and evaluation sites from current and previous monitoring efforts
Table 9.6 Methods of evaluating progress for the watershed management alternatives

ABBREVIATIONS

| | |
|---------------|---|
| AOC | Area of Concern |
| BMP | Best Management Practice |
| BOD | Biological Oxygen Demand |
| CSO | Combined Sewer Overflow |
| DO | Dissolved Oxygen |
| EPA | US Environmental Protection Agency |
| GIS | Geographic Information System |
| GLEAS | Great Lakes Environmental Assessment Section |
| IDEP | Illicit Discharge Elimination Plan |
| LID | Low Impact Development |
| MDEQ | Michigan Department of Environmental Quality |
| MDNR | Michigan Department of Natural Resources |
| MS4 | Municipal Separate Storm Sewer System |
| NPDES | National Pollutant Discharge Elimination System |
| NRCS | Natural Resources Conservation Service |
| OSDS | Onsite Sewage Disposal System |
| RAP | Remedial Action Plan |
| SCCHD | St. Clair County Health Department |
| SCCDO | St. Clair County Drain Office |
| SCCDPW | St. Clair County Department of Public Works |
| SCCRC | St. Clair County Road Commission |
| SEMCOG | Southeast Michigan Council of Governments |
| SSO | Sanitary Sewer Overflow |
| STEPL | Spreadsheet Tool for Estimating Pollutant Loads |
| TDS | Total Dissolved Solids |
| TMDL | Total Maximum Daily Load |
| TSS | Total Suspended Solids |
| USGS | United States Geological Survey |
| WAG | Watershed Advisory Group |
| WMP | Watershed Management Plan |
| WQS | Water Quality Standards |
| WWTP | Waste Water Treatment Plant |